## Model 2241 Digital Ratemeter/Scaler



## Features

- Digital Ratemeter with Built-In Scaler
- Auto-Ranging
- Adjustable Alarms
- Wide Range HV
- Overrange & Overload Protection

Model 2241 is a general purpose, digital ratemeter with a built-in scaler that facilitates timed counts over a user specified period. The LCD presents readings in a 4-digit moving decimal format together with one of a wide range of available units of measure and is accompanied by several operational and alert icons. The LCD backlight can be activated and remains lit for a user-adjustable interval. This instrument features adjustable Alert and Alarm setpoints for both the Ratemeter and Scaler modes. Front panel controls include a rotary switch for selecting between Off, Ratemeter Mode and Scaler Mode; switches for audio on/off and fast/slow response time; and push-buttons for activating the LCD backlight and for either resetting the counts or acknowledging alarms.

Specifications:

Indicated Use: General purpose survey, gross counting Compatible Detectors: GM, Proportional, Scintillation

Linearity: Reading within 10% of true value with detector connected

Display: 4-digit LCD display with 1.3 cm (0.5 in.) high digits, separate annunciators for display

units, alert, alarm, low battery, detector overload, counting overflow, and scaler counting

Display Range: Auto ranging from:

0.0 μR/hr to 9999 R/hr, 0.000 μSv/h to 9999 Sv/h

0 cpm to 999 kcpm, 0 cps to 100 kcps

Backlight: Pushbutton to activate

Ratemeter: Can display in R/hr, Sv/h, cpm, or cps when selector switch is in RATE position

Scaler: Adjustable from 1 to 9999 s (in 1 s intervals)

Alert/Alarm: Indicated by annunciation on display and audible tone

High Voltage: 400 to 2400 V

Discriminator: Adjustable from 2 to 100 mV Temperature Range: -20 to 50 °C (-4 to 122 °F)

RS-232 Port: Available in two output formats: binary output or ASCII output. The ASCII output

format option requires a firmware change (PN 4408-192).

Power: 2 "D" cell batteries housed in an externally accessible, sealed compartment Battery Life: Typically 200 hours with alkaline batteries (low battery warning on LCD)

Size: 6.5" H x 3.5" W x 8.5" L

Weight 3.5 lb

## Probe not included, Select Probe from page 111

Model 2241 Digital Ratemeter/Scaler 051-196 Check Source Cs-137 1.0 μCi 051-166 Check Source Holder

051-197 Check Source With Stick On Holder Cs-137 0.25 μCi